HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 160A1290001

BRIDGE OWNER: COFFEE COUNTY

ROAD NAME: TOM JONSON RD

CROSSING: W. FORK HICKORY CREEK

CROSSING: W. FORK HICKORY CREEK
LATITUDE:: N 35.54342 DEGREES
LONGITUDE: W 85.95430 DEGREES

COUNTY: COFFEE
ROUTE: 0A013
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.59
YEAR BUILT: 1960

		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION	
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law Enf	forcement Personnel
		[] Other:	
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or to k pier exposure, if possible, and ew the latest bridge inspection	n along curb line, both bridgents. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	nel. Use Barricade Tape, traf	eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any bi	ridge on the selected detour route shall be checked	
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substruct units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(931) 723-5100	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 728-3321	
COUNTY SHERIFF'S OFFICE	(931) 728-3591	
[] - Summarize and submit findings from the insper The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be COMMENTS:	ne inspection, a brief summary of findings and, I stream channel measurements. If significant e copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspec	tion:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole	and uninted with the fallenting management	
A 1000 Foot Roll of yellow Polyethylene Barricade T	ape printed with the following message:	

SAFETY HAZARD KEEP AWAY

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

PUBLICATION DATE

A roll of Duct Tape

07-Nov-24