HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 160A2110001

BRIDGE OWNER: CITY OF MANCHESTER
ROAD NAME: SKINNER FLAT RD
CROSSING: HUNT CREEK

LATITUDE:: N 35.45375 DEGREES LONGITUDE: W 86.05473 DEGREES

COUNTY: COFFEE
ROUTE: 0A211
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.31

LON	IGITUDE: W 86.05473 DEGREES		YEAR BUILT: 1940
		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	CONCRETE - CULVERT (INCLUDES CULVERTS)	FRAME APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE BOX TYPE ON CONCRE	TE SPREAD FOOTING FOUNDATION	N .
BENTS:	NOT APPLICABLE		
PIERS:	PIER WALL FOR CONCRETE BOX O	ON CONCRETE SPREAD FOOTING F	OUNDATION
		SCOUR EVALUATION =	
	our critical; bridge foundations de sures are installed but they are n		culated scour conditions. No scour
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
			al Maintenance Personnel
		[] THP or Local Law Ent	forcement Personnel
		[] Other:	
2. C [] - Chec [] - Chec [] - Chec	Check displacement / deflection check for plumb of piers or being the for embankment erosion in the for drift build-up on piers or the k pier exposure, if possible, are the latest bridge inspection	nts. bents nd compare to previous inspe	
[] - Stay a	ity or City Maintenance Person	nel. Use Barricade Tape, traf	cured and properly closed by District, fic cones and/or traffic flares as
•	orary measures to warn motor operly closed and barricaded.	ists to stay off of the bridge	until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
			ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
[] - The bridge units and	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT P	ERSONNEL:	TELEPHONE NUMBER:	
CITY MAYOR	t'S OFFICE	(931) 728-4652	
POLICE OFF	ICE	(931) 728-2099	
PUBLIC WOR	RKS DIRECTOR	(931) 728-6903	
The report as appropr	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Latest Bridge Ins	•	ection:	
Bridge Design Pl	ort with the above Checklist		
Tape measure w	,		
Plumb bob			
Range Pole			
A 1000 Foot Roll	of yellow Polyethylene Barricade	e Tape printed with the following message:	
	SAFETY HAZARD KE	ΈΡ ΔΜΑΥ	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape