## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 170A2900001 BRIDGE OWNER: CROCKETT COUNTY

ROAD NAME: LOVE RD

CROSSING: WHITSON CREEK

LATITUDE:: N 35.72694 DEGREES

COUNTY: CROCKETT ROUTE: 0A290 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.46

LON	NGITUDE: W 89.11194 DEGREES	YEAR BUILT: 1990	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER	LTI-BEAM OR APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUND	DATION	
PIERS:	NOT APPLICABLE		
ı		SCOUR EVALUATION	
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspectio		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.	
[ ] - Stay Cour temp	nty or City Maintenance Person orary measures to warn motor	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
-	operly closed and barricaded.	and and the state of the state	
[ ] - Conta	• •	upervisor ( if bridge is State maintained )	
		y Maintenance Official (if bridge is not State maintained)	
		ntrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	•	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



- The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.			
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 696-5460		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 696-2244		
COUNTY SHERIFF'S OFFICE	(731) 696-2104		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection Latest Bridge Inspection Report Scour POA Report with the above Checklist	on:		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
CAEETV HAZADD VEED	AMAV		

PUBLICATION DATE

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24

A roll of Duct Tape