HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: CUMBERLAND

ROUTE: 01201

LOG MILE: 0.43

SPECIAL CASE: 0

COUNTY SEQUENCE: 1

BRIDGE ID NUMBER: 18012010003

BRIDGE OWNER: CUMBERLAND COUNTY

ROAD NAME: DUNBAR RD CROSSING: BASSES CREEK

LATITUDE:: N 35.85088 DEGREES

LON	NGITUDE: W 85.05521 DEGREES	3	YEAR BUILT: 1940	
-		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM C	R GIRDER APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION		
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
	unknown foundations. Risk of so icant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
		[] TDOT District or Loca	al Maintenance Personnel	
		[] THP or Local Law En	forcement Personnel	
		[] Other:		
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during flood movement - horizontally as w Check displacement / deflection Check for plumb of piers or be ek for embankment erosion ek for drift build-up on piers or ek pier exposure, if possible, and ew the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous inspe		
<u>If Closure is</u>	recommended:			
Coun temp] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.			
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)	
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 484-6165		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 484-5424		
COUNTY SHERIFF'S OFFICE	(931) 484-6176		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection Latest Bridge Inspection Report	on:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
SAFETY HAZARD KEEP	AWAY		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)