HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: CUMBERLAND

BRIDGE ID NUMBER: 180B0180003

BRIDGE OWNER: CUMBERLAND COUNTY

ROAD NAME: OLD HWY 70

CROSSING: TANTROUGH CREEK

LATITUDE:: N 35.96366 DEGREES

LONGITUDE: W 85.14031 DEGREES

ROUTE: 0C195
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.65
YEAR BUILT: 1938

TYPE OF SUPERSTRUCTURE MAIN SPAN-**CONCRETE - TEE BEAM** APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON UNKNOWN FOUNDATION BENTS: **NOT APPLICABLE** PIERS: **NOT APPLICABLE** SCOUR EVALUATION Bridge has unknown foundations. Risk of scour cannot be determined. The bridge shall be monitored for distress during significant flood events. Monitor bridge in lieu of installing scour countermeasures. **INSPECTION PROCEDURES** [] BridgeWatch Alert What Initiated the Call-out Inspection? [1 TDOT District or Local Maintenance Personnel [] THP or Local Law Enforcement Personnel [] Other: Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate (4) TDOT Regional Bridge Engineer

PUBLICATION DATE

by a TDOT bridge inspection team.

[] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked
[] - The bridge can be re-opened only after a TD units and they are determined to be structured.	OT bridge inspection team checks the substructure ally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(931) 484-6165
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 484-5424
COUNTY SHERIFF'S OFFICE	(931) 484-6176
as appropriate, photographs of the bridge an	pection to BridgeWatch scour monitoring system. the inspection, a brief summary of findings and, id stream channel measurements. If significant be copied to Bridge Inspection Headquarters.
COMMENTS:	
Suggested List of Equipment to conduct the Inspe Latest Bridge Inspection Report	ction:
Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade	Tano printed with the following massage:
SAFETY HAZADD KEE	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24