HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 19019430001 BRIDGE OWNER: DAVIDSON COUNTY ROAD NAME: CENTRAL PIKE CROSSING: LONG CREEK

LATITUDE:: N 36.38248 DEGREES

COUNTY: DAVIDSON ROUTE: 0A989 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.00

LON	NGITUDE: W 86.91330 DEGREES		YEAR BUILT: 1960	
		TYPE OF SUPERSTRUCTURE =		
MAIN SPAN:	PRESTRESSED CONCRETE - BOX I GIRDERS - MULTIPLE	BEAM OR APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE -		
ABUTMENTS:	NTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION			
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION =		
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDURES -		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
		[] TDOT District or Loca	I Maintenance Personnel	
		[] THP or Local Law Enf	orcement Personnel	
		[] Other:		
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or beat k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar we the latest bridge inspection	n along curb line, both bridge nts. bents nd compare to previous inspe		
[] - Stay a	nty or City Maintenance Persor	nel. Use Barricade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as	
	orary measures to warn motor operly closed and barricaded.	ists to stay off of the bridge t	until such time as the bridge may	
-				
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)	
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any bi prior to signing the detour route.	ridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>C</u>	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
C	CITY MAYOR'S OFFICE	(615) 862-6000	
н	IWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 862-8700	
C	COUNTY SHERIFF'S OFFICE	(615) 862-8170	
as so			
0			
	sted List of Equipment to conduct the Inspec	tion:	
	Bridge Inspection Report		
	POA Report with the above Checklist		
_	Design Plans, if available easure with weight		
Plumb I	•		
Range			
•	Foot Roll of yellow Polyethylene Barricade T	ape printed with the following message:	
	SAFETY HAZARD KEEF		

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape