HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 20SR0690001 COUNTY: **DECATUR** ROUTE: SR069 BRIDGE OWNER: STATE OF TENNESSEE ROAD NAME: HWY 69 S SPECIAL CASE: 0 CROSSING: STEWMANS CREEK COUNTY SEQUENCE: 1

	.TITUDE:: N 35.39303 DEGREES NGITUDE: W 88.13462 DEGREES	LOG MILE: 4.90 YEAR BUILT: 1950
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - TRUSS - THRU	APPR. SPAN: CONCRETE - TEE BEAM
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE COLUMNS WITH SOLID	WEB WALL (DUMB BELL) ON CONCRETE PILE FOUNDATION
		SCOUR EVALUATION
	our critical; bridge foundations de stalled and is in good condition.	termined to be unstable for calculated scour conditions. Rip-rap protection
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	along curb line, both bridge rails and outer edge of bridge deck. its.
lf Closure is	recommended:	
Coun temp	nty or City Maintenance Person	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any bri	idge on the selected detour route shall be checked		
[] - The bridge can be re-opened only after a TDO units and they are determined to be structural	e can be re-opened only after a TDOT bridge inspection team checks the substructure		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(615) 476-8860		
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673		
TENNESSEE HIGHWAY PATROL	(731) 423-6635		
as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:		
SAFETY HAZARD KEEP	AWAY		

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT radio directory (State Personnel only)

A roll of Duct Tape