## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 22018600001
BRIDGE OWNER: DICKSON COUNTY
ROAD NAME: JONES CREEK RD
CROSSING: JONES CREEK

LATITUDE:: N 36.09048 DEGREES
LONGITUDE: W 87.36430 DEGREES

COUNTY: DICKSON
ROUTE: 01860
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.20
YEAR BUILT: 1977

LON	NGITUDE: W 87.36430 DEGREES	YEAR BUILT: 1977	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - STRII OR GIRDER	NGER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON CONCRETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		COOLID EVALUATION	
5		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to c	heck on a bridge during flood	<u>s:</u>	
1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
[ ] - Stay		cross road until bridge is secured and properly closed by District,	
temp		nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	a detour route. Any brid	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:		TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE		(615) 789-7003		
HWY. CHIEF ADMINISTRATO	R'S OFFICE	(615) 446-2638		
COUNTY SHERIFF'S OFFICE		(615) 789-4130		
The report shall include as appropriate, photogr	] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipment	to conduct the Inspectio	<u>n:</u>		
Latest Bridge Inspection Rep	ort			
Scour POA Report with the al	oove Checklist			
Bridge Design Plans, if availa	ble			
Tape measure with weight				
Plumb bob				
Range Pole				
•		e printed with the following message:		
S	SAFETY HAZARD KEEP A	WAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24