HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: DICKSON

BRIDGE ID NUMBER: 220A0280001
BRIDGE OWNER: DICKSON COUNTY
ROAD NAME: MAPLE GROVE RD
CROSSING: EAST FORK YELLOW CRE

CROSSING: EAST FORK YELLOW CREEK
LATITUDE:: N 36.16923 DEGREES
LONGITUDE: W 87 46937 DEGREES

ROUTE: 0A448

SPECIAL CASE: 0

COUNTY SEQUENCE: 1

LOG MILE: 1.29

LON	NGHUDE: W 87.46937 DEGREES		YEAR BUILT: 1979
		- TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON CONCRETE SPREAD FOOTII	NG FOUNDATION
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE SPREAD FOOTING FO	DUNDATION
		SCOUR EVALUATION =	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law Enf	orcement Personnel
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridge nts. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, traf rists to stay off of the bridge (eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	e Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



official		State District maintenance or local highway maintenance by bridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTAC	CT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY	MAYOR'S OFFICE	(615) 789-7003	
HWY. CI	HIEF ADMINISTRATOR'S OFFICE	(615) 446-2638	
COUNTY	SHERIFF'S OFFICE	(615) 789-4130	
The repart as appr] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS: _			
Latest Bridge	ist of Equipment to conduct the Inspection Report	ection:	
	n Plans, if available		
	e with weight		
Plumb bob	5		
Range Pole			
A 1000 Foot I	Roll of yellow Polyethylene Barricade	e Tape printed with the following message:	
	SAFETY HAZARD KE	EP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24