HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 230A2450001

BRIDGE OWNER: DYER COUNTY

ROAD NAME: HARNESS RD

CROSSING: BRANCH

COUNTY

ROUTE: 02722
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.25

COUNTY: DYER

	TITUDE:: N 36.13024 DEGREES	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON (CONCRETE PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	•	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
	movement - horizontally as w	-
	•	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	nts.
	k for embankment erosion	hanta
	k for drift build-up on piers or	nd compare to previous inspection
		report versus current field conditions
[] -IVevic	w the latest bridge inspection	report versus current neid conditions
<u>If Closure is</u>	recommended:	
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
		y Maintenance Official (if bridge is not State maintained)
	.,	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	-
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 286-7800		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 286-7838		
COUNTY SHERIFF'S OFFICE	(731) 285-2802		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection Latest Bridge Inspection Report Scour POA Report with the above Checklist	<u>on:</u>		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
CAFETY HAZADO MEED	A VATA V		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24