HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 23S80260003 COUNTY: DYER
BRIDGE OWNER: DYER COUNTY
ROAD NAME: UNIONVILLE RD SPECIAL CASE: 0

CROSSING: S. FK. FORKED DEER RIVER
LATITUDE:: N 35.97597 DEGREES
LONGITUDE: W 89.40097 DEGREES

COUNTY SEQUENCE: 1

LOG MILE: 3.08

LON	IGITUDE: W 89.40097 DEGREES	•	YEAR BUILT: 1956	
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/I	TYPE OF SUPERSTRUCTURE ——MULTI-BEAM OR APPR. SPAN:	CONCRETE - TEE BEAM	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON (
BENTS:	CONCRETE PILE BENT ON PILE FO			
PIERS:	RS: CONCRETE COLUMNS WITH SOLID WEB WALL (DUMB BELL) ON TIMBER PILE FOUNDATION			
		SCOUR EVALUATION —		
	our critical; bridge foundations de sures are installed but they are r	etermined to be unstable for calcu	ulated scour conditions. No scour	
		INSPECTION PROCEDURES —		
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert		
		[] TDOT District or Local	Maintenance Personnel	
		[] THP or Local Law Enfo		
		[] Other:		
[] - Span 1. C 2. C [] - Checl [] - Checl	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	ell as vertically n along curb line, both bridge i nts.		
f Closure is	recommended:			
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, trafficits to stay off of the bridge ur	red and properly closed by District, c cones and/or traffic flares as ntil such time as the bridge may	
[] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	y Maintenance Official (if brid	lge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcem	ent Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 286-7800		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 286-7838		
COUNTY SHERIFF'S OFFICE	(731) 285-2802		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	etion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade T	Tape printed with the following message:		
SAFETY HAZARD KEEP			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24