HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 24015550005
BRIDGE OWNER: FAYETTE COUNTY

ROAD NAME: JOYNERS CAMPGROUND RD

CROSSING: DRAINAGE DITCH

LATITUDE:: N 35.36394 DEGREES LONGITUDE: W 89.33622 DEGREES

COUNTY: FAYETTE
ROUTE: 01555
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.14
YEAR BUILT: 1963

LON	10110DL. W 69.33622 DEGREES	I LAN BOILT. 1903
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	INDATION
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
	Can out pec	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
	•	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection
[] - Review the latest bridge inspection report versus current field conditions		
		•
<u>lf Closure is</u>	<u>recommended:</u>	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Contact: (1) District Maintenance S		Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(901) 465-5202	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(901) 465-5232	
COUNTY SHERIFF'S OFFICE	(901) 465-3456	
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:		
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	etion:	
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade	Cano printed with the following massage:	
SAFETY HAZADD KEE		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24