HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 240A0060003
BRIDGE OWNER: FAYETTE COUNTY
ROAD NAME: FIELDS DR

CROSSING: BLACK ANKLE CREEK
LATITUDE:: N 35.27294 DEGREES

COUNTY: FAYETTE

ROUTE: 0A006

SPECIAL CASE: 0

COUNTY SEQUENCE: 1

LOG MILE: 1.72

LON	GITUDE: W 89.56144 DEGREES		YEAR BUILT: 1994	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	TYPE OF SUPERSTRUCTURE APPR. SPAN:	NOT APPLICABLE	
		TVDE 05 01100TD110T1105		
A DI ITMENTO.	TIMBER CAR ON TIMBER BU E FOU	TYPE OF SUBSTRUCTURE =		
	TIMBER CAP ON TIMBER PILE FOUN	-		
BENTS:	TIMBER PILE BENT ON PILE FOUND	DATION		
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION =		
•	nknown foundations. Risk of sco cant flood events. Monitor bridge		bridge shall be monitored for distress itermeasures.	
		INSPECTION PROCEDURES =		
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert		
	•		al Maintenance Personnel	
		[] THP or Local Law Ent	forcement Personnel	
		[] Other:		
		• •		
Things to c	heck on a bridge during floods	<u>.</u>		
1. C	movement - horizontally as we heck displacement / deflection heck for plumb of piers or ber	n along curb line, both bridge	e rails and outer edge of bridge deck.	
	k for embankment erosion			
	k for drift build-up on piers or l	pents		
	k pier exposure, if possible, an		ection	
	w the latest bridge inspection			
f Closure is	recommended:			
Coun temp	ty or City Maintenance Person	nel. Use Barricade Tape, trat	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)	
	(2) City or County Highway	y Maintenance Official (if br	ridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforce	ement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in estab		ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSON	NEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S	OFFICE	(901) 465-5202	
HWY. CHIEF ADMIN	ISTRATOR'S OFFICE	(901) 465-5232	
COUNTY SHERIFF'S	OFFICE	(901) 465-3456	
The report shall i as appropriate, p	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
Suggested List of Equ	ipment to conduct the Inspec	etion:	
Latest Bridge Inspection	on Report		
Scour POA Report with	the above Checklist		
Bridge Design Plans, it			
Tape measure with we	ight		
Plumb bob			
Range Pole			
A 1000 Foot Roll of yel	• •	Tape printed with the following message:	
	SAFETY HAZARD KEEP	P AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24