## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 240A0870001 BRIDGE OWNER: FAYETTE COUNTY ROAD NAME: BOOTHE RD

CROSSING: BRANCH

LATITUDE:: N 35.34822 DEGREES

COUNTY: FAYETTE ROUTE: 0A087 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 2.19

LON	IGITUDE: W 89.27550 DEGREES	YEAR BUILT: 1965	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	our critical; bridge foundations de sures are installed but they are n	termined to be unstable for calculated scour conditions. No scour eeded.	
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span 1. C 2. C [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts. bents	
		nd compare to previous inspection	
[ ] - Revie	ew the latest bridge inspection	report versus current field conditions	
<u>If Closure is</u>	recommended:		
] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.			
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(901) 465-5202	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(901) 465-5232	
COUNTY SHERIFF'S OFFICE	(901) 465-3456	
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>		
COMMENTS:		
Suggested List of Equipment to conduct the Inspe	ection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade		
SAFETY HAZARD KE	EP AWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24