## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 240A0970003

BRIDGE OWNER: FAYETTE COUNTY

ROAD NAME: PERRY ROAD

CROSSING: BRANCH

LATITUDE:: N 35.38454 DEGREES

ONGITUDE: W 89.20281 DEGREES

COUNTY: FAYETTE
ROUTE: 0A097
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.84

LON	IGITUDE: W 89.20281 DEGREES	YEAR BUILT: 2010	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOL	INDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to cl	<u>heck on a bridge during flood</u>	<u>s:</u>	
1. C	movement - horizontally as we have displacement / deflection check for plumb of piers or be	n along curb line, both bridge rails and outer edge of bridge deck.	
	k for embankment erosion		
	k for drift build-up on piers or	bents	
		nd compare to previous inspection	
		report versus current field conditions	
If Closure is	recommended:		
Coun temp	ity or City Maintenance Person	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(901) 465-5202		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(901) 465-5232		
COUNTY SHERIFF'S OFFICE	(901) 465-3456		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspecti	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	we writed with the fellowing measure.		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta SAFETY HAZARD KEEP			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24