HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 24F00240003

BRIDGE OWNER: STATE OF TENNESSEE
ROAD NAME: CHULAHOMA RD
CROSSING: RUSSELL CREEK

LATITUDE:: N 35.01347 DEGREES LONGITUDE: W 89.61753 DEGREES

COUNTY: FAYETTE
ROUTE: SR196
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.09
YEAR BUILT: 1939

		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF OUROTRUCTURE
ADJUTMENTO.	TIMBER OAR ON TIMBER BU E FOL	TYPE OF SUBSTRUCTURE
ABUTMENTS:		
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	red the Call-out Inspection?	[] BridgeWatch Alert
What Initiated the Call-out Inspection?		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
		[] Other.
Things to c	heck on a bridge during floods	s:
	movement - horizontally as w	
		on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	ck for embankment erosion	111.5.
	k for drift build-up on piers or	hants
	· · · · · ·	nd compare to previous inspection
		report versus current field conditions
[] - Kevie	w the latest bridge inspection	report versus current neid conditions
If Closure is	recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
		Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(901) 484-2610		
TENNESSEE HIGHWAY PATROL	(901) 543-6256		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	etion:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade T	Cano printed with the following message:		
SAFETY HAZARD KEE			
	. / 107/11		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)