HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 24\$81130025

BRIDGE OWNER: FAYETTE COUNTY

ROAD NAME: LA GRANGE RD

CROSSINC: WOLE BIVER OVER ELEMENTE.

CROSSING: WOLF RIVER OVERFLOW
LATITUDE:: N 35.12014 DEGREES
LONGITUDE: W 89.28094 DEGREES

COUNTY: FAYETTE
ROUTE: 01442
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 6.22
YEAR BUILT: 1958

		TYPE OF SUPERSTRUCTURE =		
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE -		
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION		
BENTS:	TIMBER PILE BENT ON PILE FOUND	PATION		
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION -		
Bridge is sco	our critical; bridge foundations de	termined to be unstable for calc	culated scour conditions. Rip-rap protection	
			nent of the protection system is needed.	
		INSPECTION PROCEDURES -		
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert		
•			Il Maintenance Personnel	
		[] THP or Local Law Enf	orcement Personnel	
		[] Other:		
Things to c	heck on a bridge during floods	<u>:</u>		
[] - Span	movement - horizontally as we	ell as vertically		
1. (Check displacement / deflection	າ along curb line, both bridge	e rails and outer edge of bridge deck.	
2. (Check for plumb of piers or ber	ıts.		
[] - Check for embankment erosion				
[] - Check for drift build-up on piers or bents				
[] - Check pier exposure, if possible, and compare to previous inspection				
[] - Review the latest bridge inspection report versus current field conditions				
If Ole !-				
	recommended:			
Cour temp	 Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may 			
-	operly closed and barricaded. act: (1) District Maintenance S	unervisor (if hridge is State	maintained)	
[] - 00110	• •	•	idge is not State maintained)	
		•	ment Officers as appropriate	
	(4) TDOT Regional Bridge		ment officers as appropriate	
[].The F	()	•	laylight visual inspection is made	
	TDOT bridge inspection team.	ini nie water receues and a u	ayngni visuai mopootion is made	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(901) 465-5202		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(901) 465-5232		
COUNTY SHERIFF'S OFFICE	(901) 465-3456		
The report shall include the date and time of as appropriate, photographs of the bridge a	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection Report	ection:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFFTY HAZARD KF	EP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24