HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 24SR0760019

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: SR76

CROSSING: MUDDY CREEK

COUNTY: FAYETTE ROUTE: SR076

SPECIAL CASE: 0

COUNTY SEQUENCE: 1

	TITUDE:: N 35.34211 DEGREES IGITUDE: W 89.33356 DEGREES		LOG MILE: 20.21 YEAR BUILT: 1951
		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION	
BENTS:	CONCRETE PILE BENT ON PILE FO	UNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
			culated scour conditions. Rip-rap protection
has been ins	stalled and is in fair condition. So	me minor repairs to the protect	tion system are needed.
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
1. C	Check displacement / deflectio	n along curb line, both bridg	e rails and outer edge of bridge deck.
2. 0	check for plumb of piers or be	nts.	
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or	bents	
[] - Chec	k pier exposure, if possible, ar	nd compare to previous inspe	ection
[] - Revie	w the latest bridge inspection	report versus current field c	conditions
If Clasura is	recommended:		
Coun	ity or City Maintenance Persor	nel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
be pr	operly closed and barricaded.		-
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ith State District maintenance or local highway maintenance Any bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(901) 484-2610		
TENNESSEE HIGHWAY PATROL	(901) 543-6256		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the In	nspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	cade Tape printed with the following message:		
SAFETY HAZARD	KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24