## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: FENTRESS

BRIDGE ID NUMBER: 250A0630001
BRIDGE OWNER: FENTRESS COUNTY
ROAD NAME: WOLF RIVER LOOP
CROSSING: ROTTEN FORK WOLF RIVER
LATITUDE:: N 36.53924 DEGREES

ROUTE: 0A063
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.42

LON	NGITUDE: W 84.94856 DEGREES	YEAR BUILT: 1939
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	
		TYPE OF SUBSTRUCTURE
ARITMENTS:	CONCRETE FULL HEIGHT ABUTME	
BENTS:	NOT APPLICABLE	NI ON UNKNOWN FOUNDATION
PIERS:	NOT APPLICABLE	
TILINO.	NOT AFFLICABLE	
		SCOUR EVALUATION ————————————————————————————————————
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES -
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or being the control of th	n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	Il work with State District maintenance or local highway maintenance ur route. Any bridge on the selected detour route shall be checked te.		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 879-7713		
HWY. CHIEF ADMINISTRATOR'S OFFI	ICE (931) 879-7913		
COUNTY SHERIFF'S OFFICE	(931) 879-8142		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to cond	duct the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Ch	ecklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	ene Barricade Tape printed with the following message:		
SAFFTY	HAZARD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24