HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 27015850005
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: SALEM CHURCH RD.

CROSSING: OVERFLOW

LATITUDE:: N 35.95806 DEGREES LONGITUDE: W 88.73797 DEGREES

COUNTY: GIBSON
ROUTE: 01585
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.36

| LON | NGITUDE: W 88.73797 DEGREES | YEAR BUILT: 1971 | |
|--|--|--|--|
| MAIN SPAN: | CONCRETE - CHANNEL BEAM | TYPE OF SUPERSTRUCTURE APPR. SPAN: NOT APPLICABLE | |
| | | TYPE OF SUBSTRUCTURE | |
| ABUTMENTS: | TIMBER CAP ON TIMBER PILE FOU | | |
| BENTS: | TIMBER PILE BENT ON PILE FOUND | | |
| PIERS: | NOT APPLICABLE | | |
| | 1101711121071322 | GOOUR EVALUATION | |
| 5 | | SCOUR EVALUATION | |
| | our critical; bridge foundations de sures are installed but they are n | termined to be unstable for calculated scour conditions. No scour eeded. | |
| | | INSPECTION PROCEDURES ———————————————————————————————————— | |
| What Initiated the Call-out Inspection? | | [] BridgeWatch Alert | |
| | | [] TDOT District or Local Maintenance Personnel | |
| | | [] THP or Local Law Enforcement Personnel | |
| | | [] Other: | |
| [] - Span 1. C 2. C [] - Chec [] - Chec | Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an | ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts. | |
| <u>If Closure is</u> | recommended: | | |
| Coun temp | nty or City Maintenance Person | cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may | |
| [] - Conta | act: (1) District Maintenance S | upervisor (if bridge is State maintained) | |
| | (2) City or County Highwa | y Maintenance Official (if bridge is not State maintained) | |
| | (3) Tennessee Highway Pa | atrol and/or local law enforcement Officers as appropriate | |
| | (4) TDOT Regional Bridge | Engineer | |
| |] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. | | |

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



| The bridge inspection team will work with State D officials in establishing a detour route. Any bridge prior to signing the detour route. | | | |
|---|---|--|--|
| | The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. | | |
| CONTACT PERSONNEL: | TELEPHONE NUMBER: | | |
| COUNTY MAYOR'S OFFICE | (731) 855-7611 | | |
| HWY. CHIEF ADMINISTRATOR'S OFFICE | (731) 855-7684 | | |
| COUNTY SHERIFF'S OFFICE | (731) 855-1121 | | |
| Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. | | | |
| COMMENTS: | | | |
| Suggested List of Equipment to conduct the Inspection | <u>:</u> | | |
| Latest Bridge Inspection Report | | | |
| Scour POA Report with the above Checklist | | | |
| Bridge Design Plans, if available | | | |
| Tape measure with weight | | | |
| Plumb bob | | | |
| Range Pole | | | |
| A 1000 Foot Roll of yellow Polyethylene Barricade Tape | | | |
| SAFETY HAZARD KEEP AV | VAY | | |

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24