HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: GIBSON

BRIDGE ID NUMBER: 27015930013
BRIDGE OWNER: GIBSON COUNTY

ROAD NAME: OLD TRENTON-DRESDEN RD
CROSSING: SOUTH FORK OBION RIVER
LATITUDE:: N 36.12819 DEGREES
LONGITUDE: W 88.84972 DEGREES

ROUTE: 01593
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 8.04

LON	IGITUDE: W 88.84972 DEGREES	3	YEAR BUILT: 1988	
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/	MULTI-BEAM OR APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	CONCRETE PILE FOUNDATION		
BENTS:	CONCRETE COLUMN FOUR OR MORE POST BENT ON PILE FOUNDATION			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
	inknown foundations. Risk of scicant flood events. Monitor bridg		bridge shall be monitored for distress ntermeasures.	
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection		[] BridgeWatch Alert		
	·	-	al Maintenance Personnel	
		[] THP or Local Law En	forcement Personnel	
		[] Other:		
Things to cl	heck on a bridge during flood	<u>s:</u>		
[] - Span	movement - horizontally as w	ell as vertically		
	· · · · · · · · · · · · · · · · · · ·	•	e rails and outer edge of bridge deck.	
	Check for plumb of piers or be		, o ramo uma o unon o ugo on um ugo ucom	
	k for embankment erosion			
	k for drift build-up on piers or	bents		
	k pier exposure, if possible, a		ection	
	w the latest bridge inspection	· · · · · · · · · · · · · · · · · · ·		
[]	in the latest shage mepocher	roport volcue cultoni noia c		
f Closure is	recommended:			
[] - Stav a	at bridge with vehicle pulled a	cross road until bridge is see	cured and properly closed by District,	
	ty or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as			
-	-		until such time as the bridge may	
-	operly closed and barricaded			
[] - Conta	ct: (1) District Maintenance Supervisor(if bridge is State maintained)			
	` ' ' '	·	ridge is not State maintained)	
	, ,		ement Officers as appropriate	
	(4) TDOT Regional Bridge	•		
	Bridge should remain closed u FDOT bridge inspection team.		daylight visual inspection is made	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any bridge prior to signing the detour route. 	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 855-7611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHERIFF'S OFFICE	(731) 855-1121		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>n:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	e printed with the following message:		
SAFETY HAZARD KEEP A			

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

PUBLICATION DATE
07-Nov-24

A roll of Duct Tape