HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 27029990001 BRIDGE OWNER: CITY OF HUMBOLDT

ROAD NAME: N 6TH AVE CROSSING: BRANCH

COUNTY: GIBSON ROUTE: 0B132 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.06

	NGITUDE:: N 35.82103 DEGREES NGITUDE: W 88.92317 DEGREES	LOG MILE: 0.06 YEAR BUILT: 1984
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - BOX E	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
BENTS:	CONCRETE PILE BENT ON PILE FO	UNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec [] - Revie	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an ew the latest bridge inspection	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. hts.
<u>If Closure is</u>	recommended:	
Coun temp	ity or City Maintenance Person	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)		
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(731) 784-2511		
POLICE OFFICE	(731) 784-1322		
as appropriate, photographs of the bridge a	spection to BridgeWatch scour monitoring system. If the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Inspe	ection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFETY HAZARD KE	EP AWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			
Traffic Safety Flares - Minimum of four (4) or set o	•		
TDOT two-way radio (State Personnel only) and/or	r cellular telephone		

TDOT radio directory (State Personnel only)