## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



COUNTY: GIBSON

BRIDGE ID NUMBER: 270A0390001 BRIDGE OWNER: GIBSON COUNTY ROAD NAME: FLETCHER RD

CROSSING: BR OF N FORK FORKED DEER

ROUTE: 0A039 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

LATITUDE:: N 36.02303 DEGREES LONGITUDE: W 89.03414 DEGREES		LOG MILE: 1.40 YEAR BUILT: 1975
	TYPE OF SUPERSTRUCTURE =	
MAIN SPAN: WOOD OR TIMBER - STRINGER/MUL GIRDER		NOT APPLICABLE
	TYPE OF SUBSTRUCTURE -	
ABUTMENTS: TIMBER CAP ON TIMBER PILE FOUN	NDATION	
BENTS: NOT APPLICABLE		
PIERS: NOT APPLICABLE		
	SCOUR EVALUATION =	
Bridge has unknown foundations. Risk of sco		
during significant flood events. Monitor bridge	in lieu of installing scour coun	itermeasures.
	INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?	[ ] BridgeWatch Alert	
	[ ] TDOT District or Loca	al Maintenance Personnel
	[ ] THP or Local Law En	forcement Personnel
	[ ] Other:	
Things to check on a bridge during floods	<u>:</u>	
[ ] - Span movement - horizontally as we	ll as vertically	
-		e rails and outer edge of bridge deck.
2. Check for plumb of piers or ben	ts.	
[ ] - Check for embankment erosion		
[ ] - Check for drift build-up on piers or k		_
[ ] - Check pier exposure, if possible, and		
[ ] - Review the latest bridge inspection	report versus current field c	onditions
If Closure is recommended:		
	ross road until bridge is see	oured and properly closed by District
[ ] - Stay at bridge with vehicle pulled ac County or City Maintenance Person		
temporary measures to warn motori		
be properly closed and barricaded.		
[ ] - Contact: (1) District Maintenance Su	•	•
	•	ridge is not State maintained )
		ement Officers as appropriate
(4) TDOT Regional Bridge	•	
<ul><li>[ ] - The Bridge should remain closed un by a TDOT bridge inspection team.</li></ul>	itil the water recedes and a d	daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked
	can be re-opened only after a T hey are determined to be struct	DOT bridge inspection team checks the substructure urally stable.
CONTACT PE	RSONNEL:	TELEPHONE NUMBER:
COUNTY MAY	OR'S OFFICE	(731) 855-7611
HWY. CHIEF	ADMINISTRATOR'S OFFICE	(731) 855-7684
COUNTY SHE	RIFF'S OFFICE	(731) 855-1121
The report s	shall include the date and time o ate, photographs of the bridge a	nspection to BridgeWatch scour monitoring system.  of the inspection, a brief summary of findings and,  and stream channel measurements. If significant  o be copied to Bridge Inspection Headquarters.
COMMENTS:		
Suggested List of	f Equipment to conduct the Insp	pection:
Latest Bridge Ins	pection Report	
Scour POA Repor	rt with the above Checklist	
Bridge Design Pla	ans, if available	
Tape measure wi	th weight	
Plumb bob		
Range Pole		
A 1000 Foot Roll	•	e Tape printed with the following message:
	SAFETY HAZARD KE	EEP AWAY

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24