HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270A0440003
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: ESQ GREEN RD

CROSSING: DRAINAGE DITCH - COW CR.
LATITUDE:: N 36.06903 DEGREES
ONGITUDE: W 89.04767 DEGREES

ROUTE: 0A044
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.99

COUNTY: GIBSON

LON	NGITUDE: W 89.04767 DEGREES		YEAR BUILT: 1997
MAIN SPAN:	CONCRETE - CHANNEL BEAM	TYPE OF SUPERSTRUCTURE APPR. SPAN:	NOT APPLICABLE
ADUTACATO	THE P. C. P. C. V. THE P. P. V. F. CO.	TYPE OF SUBSTRUCTURE =	
	TIMBER CAP ON TIMBER PILE FOU	-	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION =	
-	our critical; bridge foundations de ling scour countermeasures.	termined to be unstable for cal	culated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		-	al Maintenance Personnel
		[] THP or Local Law Ent	
Things to c	heck on a bridge during floods	<u>s:</u>	
1. (•	n along curb line, both bridge	e rails and outer edge of bridge deck.
	Check for plumb of piers or be	its.	
	k for embankment erosion	honte	
	k for drift build-up on piers or		action
	k pier exposure, if possible, ar	· · · · · · · · · · · · · · · · · · ·	
[] - Revie	ew the latest bridge inspection	report versus current field c	onditions
If Closure is	recommended:		
[] - Stay : Coun temp	at bridge with vehicle pulled a	nel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Contact: (1) District Maintenance Supervisor (if bridge is			maintained)
[] 00	• •	• •	ridge is not State maintained)
	() ,	•	ement Officers as appropriate
	(4) TDOT Regional Bridge		
[].The F	()	•	daylight visual inspection is made
	TDOT bridge inspection team.	inii iilo watoi icocucs ailu a t	adyngint violati mopeotion to made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any bri	idge on the selected detour route shall be checked		
	oridge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 855-7611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHERIFF'S OFFICE	(731) 855-1121		
as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:		
SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24