HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270A2540001

BRIDGE OWNER: GIBSON COUNTY

ROAD NAME: WILCAT LANE RD

CROSSING: LOCUST GROVE CREEK

LATITUDE:: N 36.09906 DEGREES

COUNTY: GIBSON
ROUTE: 0A254
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.46
YEAR BUILT: 1978

LONGITUDE: W 88.84144 DEGREES		YEAR BUILT: 1978	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX I GIRDERS - MULTIPLE	BEAM OR APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION ————————————————————————————————————	
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	·	[] TDOT District or Local Maintenance Personnel	
		THP or Local Law Enforcement Personnel	
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or being the control of th	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
lf Closure is	recommended:		
[] - Stay Cour temp	at bridge with vehicle pulled a nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any br	ridge on the selected detour route shall be checked		
	e bridge can be re-opened only after a TDOT bridge inspection team checks the substructure its and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 855-7611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHERIFF'S OFFICE	(731) 855-1121		
as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspect	tion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:		
SAFETY HAZARD KEEP	PAWAY		

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)