## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270A3640001
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: POWELL RD

CROSSING: DITCH

ROUTE: 0A364
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.04

COUNTY: GIBSON

	TITUDE:: N 36.03317 DEGREE	
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MI GIRDER	TYPE OF SUPERSTRUCTURE  ULTI-BEAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FO	JNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress ge in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
Things to o	heck on a bridge during flood	· ·
_		
	movement - horizontally as w	-
	<u>-</u>	on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be k for embankment erosion	ints.
	k for drift build-up on piers or	· hents
	· · · · · · · · · · · · · · · · · · ·	nd compare to previous inspection
		n report versus current field conditions
[ ] .terie	o .a.oot bagoopooo.	
lf Closure is	recommended:	
Coun temp	ty or City Maintenance Perso	across road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[ ] - Conta	act: (1) District Maintenance	Supervisor ( if bridge is State maintained )
	(2) City or County Highwa	ay Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway F	Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 855-7611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHERIFF'S OFFICE	(731) 855-1121		
The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.  COMMENTS:			
Suggested List of Equipment to conduct the Inspect	tion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A roll of Duct Tape