HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 28\$62340007 BRIDGE OWNER: GILES COUNTY ROAD NAME: PROSPECT RD CROSSING: RICHLAND CREEK

COUNTY: GILES ROUTE: 00981 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.11250 DEGREE: NGITUDE: W 87.00277 DEGREE:	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE CONTI BEAM OR GIRDERS - SINGLE OR S	
		TYPE OF SUBSTRUCTURE
	CONCRETE STUB ABUTMENT ON	STEEL PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE HAMMERHEAD PIER C	IN STEEL PILE FOUNDATION
		SCOUR EVALUATION
	our critical; bridge foundations de ling scour countermeasures.	etermined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
This was to all		
_	<u>heck on a bridge during flood</u>	
	movement - horizontally as w	•
	<u>-</u>	on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	nts.
	k for embankment erosion k for drift build-up on piers or	honte
	•	nd compare to previous inspection
		report versus current field conditions
[] - Kevie	w the latest bridge inspection	Treport versus current neid conditions
If Closure is	recommended:	
Coun temp	ity or City Maintenance Person	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	,,,,,	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	_
	Bridge should remain closed เ TDOT bridge inspection team.	Intil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a c	detour route. Any bridge on the selected detour route shall be checked route.	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(931) 363-5300	
HWY. CHIEF ADMINISTRATOR'S	OFFICE (931) 363-1635	
COUNTY SHERIFF'S OFFICE	(931) 363-2460	
The report shall include the as appropriate, photograph scouring has occurred, the	dings from the inspection to BridgeWatch scour monitoring system. e date and time of the inspection, a brief summary of findings and, ns of the bridge and stream channel measurements. If significant report shall also be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to	conduct the Inspection:	
Latest Bridge Inspection Report		
Scour POA Report with the above		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
•	thylene Barricade Tape printed with the following message:	
SAF	ETY HAZARD KEEP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19