## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 300A5540001
BRIDGE OWNER: GREENE COUNTY
ROAD NAME: OLD JONESBORO RD
CROSSING: HORSE CREEK

LATITUDE:: N 36.16212 DEGREES
LONGITUDE: W 82.70102 DEGREES

COUNTY: GREENE
ROUTE: 0A554
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.24
YEAR BUILT: 1975

LON	IGITUDE: W 82.70102 DEGREES	YEAR BUILT: 1975	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM C	R GIRDER APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON (	CONCRETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge is sco	our critical, but countermeasures	have been installed to reduce the risk of bridge failure during a floor	od
event. Deter		riprap should be reported to TDOT for assessment. Monitor bridge	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	ell as vertically n along curb line, both bridge rails and outer edge of bridge d nts.	eck.
f Closure is	recommended:		
Coun temp	ty or City Maintenance Persor	cross road until bridge is secured and properly closed by Dist inel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
		atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	<del>-</del>	
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made	<b>;</b>

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	will work with State District maintenance or local highway maintenance stour route. Any bridge on the selected detour route shall be checked oute.		
[ ] - The bridge can be re-opened units and they are determined	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
<b>CONTACT PERSONNEL:</b>	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 798-1766		
HWY. CHIEF ADMINISTRATOR'S O	FFICE (423) 798-1747		
COUNTY SHERIFF'S OFFICE	(423) 798-1800		
The report shall include the cas appropriate, photographs	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to co	onduct the Inspection:		
Latest Bridge Inspection Report	Observices		
Scour POA Report with the above	Checklist		
Bridge Design Plans, if available			
Tape measure with weight Plumb bob			
Range Pole			
<u> </u>	ylene Barricade Tape printed with the following message:		
	TV HAZADD KEED AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24