HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 300A6640001

BRIDGE OWNER: GREENE COUNTY

ROAD NAME: CHANDLER CIR

CROSSING: PAINT CREEK

LATITUDE:: N 35.99743 DEGREES
LONGITUDE: W 82.78647 DEGREES

COUNTY: GREENE
ROUTE: 0A664
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.02
YEAR BUILT: 2000

LON	NGHODE. W 62.76047 DEGREES	TEAR BOILT. 2000
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has u	unknown foundations. Risk of sco	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ad the Call-out Inspection?	[] BridgeWatch Alert
What Initiated the Call-out Inspection?		[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
		[] Other.
Things to c	heck on a bridge during floods	<u>s:</u>
_	movement - horizontally as w	
	•	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	bents
		nd compare to previous inspection
		report versus current field conditions
[]		
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Contact: (1) District Maintenanc		supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance by bridge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(423) 798-1766	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 798-1747	
COUNTY SHERIFF'S OFFICE	(423) 798-1800	
The report shall include the date and time as appropriate, photographs of the bridge	nspection to BridgeWatch scour monitoring system. of the inspection, a brief summary of findings and, and stream channel measurements. If significant so be copied to Bridge Inspection Headquarters.	
COMMENTS:		
Suggested List of Equipment to conduct the Ins	pection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricac	de Tape printed with the following message:	
SAFETY HAZARD K	EEP AWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)