HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 310A4300001

BRIDGE OWNER: GRUNDY COUNTY

ROAD NAME: STELLA SCRUGGS RD

CROSSING: PEPPER HOLLOW BRANCH

LATITUDE:: N 35.49847 DEGREES

COUNTY: GRUNDY
ROUTE: 0A430
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.09
YEAR BUILT: 1940

LON	NGHODE. W 65.65406 DEGREES	TEAR BOILT. 1940
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has I	inknown foundations. Risk of soc	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
TTIME IIIII.	ou mo our sur mopositor.	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
		n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
		report versus current field conditions
<u>lf Closure is</u>	recommended:	
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



- The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.		
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
TELEPHONE NUMBER:		
(931) 692-3718		
(931) 592-3751		
(931) 692-3466		
[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
rinted with the following message:		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24

BRIDGE ID 310A4300001