HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 330C6050001

BRIDGE OWNER: CITY OF RED BANK

ROAD NAME: MIDVALE AVE E

CROSSING: STRINGERS BRANCH

LATITUDE:: N 35.08910 DEGREES

LONGITUDE: W 85.31215 DEGREES

COUNTY: HAMILTON
ROUTE: 0C605
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.43
YEAR BUILT: 1940

		TYPE OF SUPERS	STRUCTURE -		
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBST	RUCTURE -		
ABUTMENTS:	MASONRY OR CONCRETE BLOCK			DATION	
BENTS:	NOT APPLICABLE				
PIERS:	NOT APPLICABLE				
		CCOUR EVAL	LIATION		
Duidae bee	unknown formaletions. Disk of one	SCOUR EVAL		huidan ahall ha waanitayad fay diatyoon	
-	unknown foundations. Risk of sco ficant flood events. A permanent			bridge shall be monitored for distress ve system has been installed.	
			·		
		- INSPECTION PRO			
What Initiated the Call-out Inspection?			atch Alert		
				al Maintenance Personnel	
				forcement Personnel	
		[] Other: _			
Things to c	heck on a bridge during floods				
_					
	movement - horizontally as w	•		and and automotive of helding deal	
	•	_	e, both briage	e rails and outer edge of bridge deck.	
	Check for plumb of piers or be	nts.			
	k for embankment erosion	hanta			
	k for drift build-up on piers or		raviaua inana	action	
	k pier exposure, if possible, ar		-		
[] - Revie	ew the latest bridge inspection	report versus c	urrent field Co	onditions	
If Closure is	recommended:				
		cross road until	bridge is sec	cured and properly closed by District,	
	•		_	fic cones and/or traffic flares as	
			of the bridge u	until such time as the bridge may	
-	roperly closed and barricaded.				
[] - Cont	act: (1) District Maintenance S	•	•	•	
	`, '	•	•	idge is not State maintained)	
			I law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	_			
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials	• .	ith State District maintenance or local highway maintenance Any bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT	PERSONNEL:	TELEPHONE NUMBER:		
CITY MAY	OR'S OFFICE	(423) 877-1103		
POLICE O	FFICE	(423) 877-1103		
PUBLIC W	ORKS DIRECTOR	(423) 877-1103		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS: 				
	t of Equipment to conduct the I	Inspection:		
Scour POA Re	port with the above Checklist			
•	Plans, if available			
Tape measure	with weight			
Plumb bob				
Range Pole				
A 1000 Foot Ro		cade Tape printed with the following message:		
	SAFETY HAZARD	KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24