HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 330C7750001
BRIDGE OWNER: CITY OF RED BANK
ROAD NAME: KILDARE ST

CROSSING: STRINGERS BRANCH
LATITUDE:: N 35.09287 DEGREES
LONGITUDE: W 85.30847 DEGREES

COUNTY: HAMILTON
ROUTE: 0C775
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.04
YEAR BUILT: 1950

		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTM	ENT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		cour cannot be determined. The bridge shall be monitored for distress ge in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers on k pier exposure, if possible, a	on along curb line, both bridge rails and outer edge of bridge deck. ents.
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Perso	across road until bridge is secured and properly closed by District, onnel. Use Barricade Tape, traffic cones and/or traffic flares as orists to stay off of the bridge until such time as the bridge may l.
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
		Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	ne Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	with State District maintenance or local highway maintenance te. Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(423) 877-1103		
POLICE OFFICE	(423) 877-1103		
PUBLIC WORKS DIRECTOR	(423) 877-1103		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the	ne Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklis	st .		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	rricade Tape printed with the following message:		
SAFETY HAZA	RD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24