HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: HAMILTON

BRIDGE ID NUMBER: 330D7810001
BRIDGE OWNER: HAMILTON COUNTY
ROAD NAME: COULTERVILLE RD
CROSSING: SALE CREEK

LATITUDE:: N 35.42660 DEGREES

ROUTE: 0D781
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.60

LON	NGITUDE: W 85.09015 DEGREES	YEAR BUILT: 1955
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/N	IULTI-BEAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON U	NKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES ————————————————————————————————————
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
 The bridge can be re-opened only after a TDOT units and they are determined to be structurally 	e can be re-opened only after a TDOT bridge inspection team checks the substructure they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 209-6100		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 855-6106		
PUBLIC WORKS DIRECTOR	(423) 209-7899		
COUNTY SHERIFF'S OFFICE	(423) 209-7000		
The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	stream channel measurements. If significant copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspecti	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			

PUBLICATION DATE

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

07-Nov-24