HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 350A1670001

BRIDGE OWNER: HARDEMAN COUNTY
ROAD NAME: ESSARY SPRINGS RD
CROSSING: BEARMAN CREEK

LATITUDE:: N 35.00821 DEGREES LONGITUDE: W 88.79479 DEGREES

COUNTY: HARDEMAN
ROUTE: 0A167
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.57

LON	IGITUDE: W 88.79479 DEGREES	YEAR BU	LT: 1960	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	TYPE OF SUPERSTRUCTURE APPR. SPAN: NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU			
BENTS:	TIMBER PILE BENT ON PILE FOUN			
PIERS:	NOT APPLICABLE			
TIENO.	NOT ALL LICABLE			
		SCOUR EVALUATION ————————————————————————————————————		
		our cannot be determined. The bridge shall be monitoned in lieu of installing scour countermeasures.	ed for distress	
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
		[] TDOT District or Local Maintenance Perso	nnel	
		[] THP or Local Law Enforcement Personnel		
		[] Other:		
1. C 2. C [] - Chec [] - Chec [] - Chec	Check for plumb of piers or bei k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge nts.	of bridge deck.	
<u>If Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly clonel. Use Barricade Tape, traffic cones and/or traffists to stay off of the bridge until such time as the	ic flares as	
[] - Conta	[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	y Maintenance Official (if bridge is not State mai	ntained)	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as app	ropriate	
	(4) TDOT Regional Bridge	Engineer		
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



District maintenance or local highway maintenance ge on the selected detour route shall be checked			
The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
TELEPHONE NUMBER:			
(731) 658-3266			
(731) 658-5102			
(731) 658-3971			
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
<u>n:</u>			
e printed with the following message:			
WAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24