HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A0100001 BRIDGE OWNER: TOWN OF CRUMP ROAD NAME: SEATON LOOP CROSSING: BEASON CREEK

COUNTY: HARDIN ROUTE: 0A010 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	.TITUDE:: N 35.22467 DEGREE: Igitude: W 88.33847 Degree:		
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/		
	GIRDER		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMI	ENT ON SOIL FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONCRETE SPREAD FOOTING FOUNDATION	
		SCOUR EVALUATION	
is required to		that extensive scour has occurred at bridge foundations. Immediate action es. Rip-rap protection has been installed and is in fair condition. Some eeded.	
		- INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	vell as vertically on along curb line, both bridge rails and outer edge of bridge deck. onts.	
lf Closure is	recommended:		
Coun temp	ty or City Maintenance Perso	ncross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.	
[] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)		
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	e Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(731) 632-4224		
POLICE OFFICE	(731) 632-0707		
[] - Summarize and submit findings from the inspe The report shall include the date and time of th as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e inspection, a brief summary of findings and, stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspecti	i <u>on:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)