HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A0280001
BRIDGE OWNER: HARDIN COUNTY
ROAD NAME: TAYLOR RD
CROSSING: CHALK CREEK

LATITUDE:: N 35.28639 DEGREES
LONGITUDE: W 88.30328 DEGREES

COUNTY: HARDIN
ROUTE: 0A028
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.62
YEAR BUILT: 1884

LON	NGHODE. W 66.30326 DEGREES	TEAN BOILT. 1904
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	INDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge is sco	our critical: bridge foundations de	etermined to be unstable for calculated scour conditions. Monitor bridge in
	ling scour countermeasures.	semined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
1. 0	Check displacement / deflectio	n along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspection
[] - Revie	ew the latest bridge inspection	report versus current field conditions
	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



e inspection team checks the substructure e.
TELEPHONE NUMBER:
(731) 925-9078
(731) 925-4993
(731) 925-3377
ection, a brief summary of findings and, channel measurements. If significant to Bridge Inspection Headquarters.
ated with the following massage:
nted with the following message:

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24