## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A0810001
BRIDGE OWNER: HARDIN COUNTY
ROAD NAME: HURRICANE DR
CROSSING: DRAINAGE DITCH

LATITUDE:: N 35.40753 DEGREES
LONGITUDE: W 88.32075 DEGREES

COUNTY: HARDIN
ROUTE: 0A081
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.70
YEAR BUILT: 1931

20.	10.100 DIONE	•		12/40/201211. 1991
		TYPE OF SUPER	STRUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBS	TRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON SOIL FOUN	IDATION	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
			=	
		SCOUR EVA		
	unknown foundations. Risk of sco icant flood events. No scour cou			bridge shall be monitored for distress they are needed.
		INSPECTION PR	ROCEDURES -	
What Initiat	ed the Call-out Inspection?	[ ] BridgeV	Vatch Alert	
	·	•		al Maintenance Personnel
		[ ] THP or	Local Law En	forcement Personnel
1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or beat k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar we the latest bridge inspection	n along curb lir nts. bents nd compare to p	ne, both bridg orevious insp	
	recommended:	oross road unti	l bridge is see	burned and proporty placed by District
Coun temp	nty or City Maintenance Persor	nnel. Use Barric	ade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	supervisor ( if b	oridge is State	maintained )
	(2) City or County Highwa	y Maintenance	Official ( if bi	ridge is not State maintained )
	(3) Tennessee Highway Pa	atrol and/or loc	al law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PE	RSONNEL:	TELEPHONE NUMBER:		
COUNTY MAY	OR'S OFFICE	(731) 925-9078		
HWY. CHIEF A	ADMINISTRATOR'S OFFICE	(731) 925-4993		
COUNTY SHE	RIFF'S OFFICE	(731) 925-3377		
The report s	] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
Suggested List of	Equipment to conduct the Insp	ection:		
Latest Bridge Ins	pection Report			
Scour POA Repor	t with the above Checklist			
Bridge Design Pla	ıns, if available			
Tape measure wit	h weight			
Plumb bob				
Range Pole				
A 1000 Foot Roll of	•	e Tape printed with the following message:		
	SAFETY HAZARD KE	EP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24