## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A1440001
BRIDGE OWNER: HARDIN COUNTY
ROAD NAME: TOMBAKER CR
CROSSING: SHORT CREEK

LATITUDE:: N 35.38803 DEGREES
LONGITUDE: W 88.04458 DEGREES

ROUTE: 0A144
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.43
YEAR BUILT: 1945

COUNTY: HARDIN

LOI	NGITUDE. W 66.04436 DEGREES		TEAR BOILT. 1943
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT AP	PLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON SOIL FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONCRETE SPREAD FOOTING FOUNDATION	ı
		SCOUR EVALUATION	
Bridge is sco	our critical, but countermeasures	have been installed to reduce the risk of	f bridge failure during a flood
event. Deter	rioration of channel protection or	riprap should be reported to TDOT for a cant repairs to the protection system are	ssessment. Rip-rap protection has
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Local Mainte	nance Personnel
		[ ] THP or Local Law Enforcement	nt Personnel
		[ ] Other:	
1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or bench for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails ar nts.	
If Closure is	recommended:		
Cour temp	nty or City Maintenance Person	cross road until bridge is secured and nel. Use Barricade Tape, traffic cone ists to stay off of the bridge until suc	s and/or traffic flares as
[ ] - Contact: (1) District Maintenance Supervisor (if bridge is State ma			ned)
	(2) City or County Highwa	y Maintenance Official (if bridge is r	ot State maintained )
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Of	ficers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any b prior to signing the detour route.	ridge on the selected detour route shall be checked	
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 925-9078	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 925-4993	
COUNTY SHERIFF'S OFFICE	(731) 925-3377	
Suggested List of Equipment to conduct the Inspec	etion:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade T		
SAFETY HAZARD KEEP	PAWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24