## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUM	BER: 3	60A2370001			COUNTY:	HARDIN	
BRIDGE OWNER: HARDIN COUNTY					ROUTE:	01742	
ROAD N	IAME: C	HERRY CHAP	EL LP		SPECIAL CASE:	0	
CROS	SING: LI	EFT FORK WI	HITES CREEK		COUNTY SEQUENCE:	1	
LATIT	UDE:: N	l 35.09444	DEGREES		LOG MILE:	7.64	
LONGIT	TUDE: V	88.06072	DEGREES		YEAR BUILT:	1970	
				TYPE OF SUPERSTRUCTURE			
MAIN SPAN: CO	ONCRET	E - CHANNEL	BEAM	APPR. SPAN:	NOT APPLICABLE		
				TYPE OF SUBSTRUCTURE			
ABUTMENTS: TI	MBER C	AP ON TIMBE	R PILE FOUN	DATION			
BENTS: SI	STEEL PILE BENT ON PILE FOUNDATION						
PIERS: NO	OT APPL	ICABLE					
				SCOUR EVALUATION			
Bridge is scour countermeasure		-		ermined to be unstable for cal eded.	culated scour conditions. I	No scour	
				INSPECTION PROCEDURES -			
What Initiated	the Ca	II-out Inspe	ction?	[ ] BridgeWatch Alert			
		-		[] TDOT District or Loca	al Maintenance Personne	el	
				[ ] THP or Local Law Enf	forcement Personnel		

[ ] Other: \_\_\_\_

## Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
  - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.
  - 2. Check for plumb of piers or bents.
- [ ] Check for embankment erosion
- [ ] Check for drift build-up on piers or bents
- [] Check pier exposure, if possible, and compare to previous inspection
- [ ] Review the latest bridge inspection report versus current field conditions

## If Closure is recommended:

- [] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [] Contact: (1) District Maintenance Supervisor (if bridge is State maintained)
  - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
  - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
  - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

Р	U	в	LI	C	A٦	<b>FI</b> (	O	Ν	D	AT	Έ
•	-	-	_	-							

07-Nov-24

BRIDGE ID 360A2370001



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(731) 925-9078
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 925-4993
COUNTY SHERIFF'S OFFICE	(731) 925-3377

[ ] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS: \_\_\_\_\_

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report

Scour POA Report with the above Checklist

Bridge Design Plans, if available

Tape measure with weight

Plumb bob

**Range Pole** 

A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message:

## SAFETY HAZARD KEEP AWAY

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICATION DATE