HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 36SR1420003

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: **SR142**CROSSING: **LICK CREEK**

LATITUDE:: N 35.08981 DEGREES
LONGITUDE: W 88.35297 DEGREES

COUNTY: HARDIN
ROUTE: SR142
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.78
YEAR BUILT: 1947

LON	NGHODE. W 86.33297 DEGREES	TEAN BOILT. 1947		
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	CONCRETE PILE FOUNDATION		
BENTS:	CONCRETE PILE BENT ON PILE FO	RETE PILE BENT ON PILE FOUNDATION		
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
Bridge is see	our critical: bridge foundations de	etermined to be unstable for calculated scour conditions. Rip-rap protection		
	stalled and is in good condition.	stermined to be unstable for calculated scour conditions. Rip-rap protection		
		INSPECTION PROCEDURES -		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
		[] TDOT District or Local Maintenance Personnel		
		[] THP or Local Law Enforcement Personnel		
		[] Other:		
Things to c	heck on a bridge during floods	<u>S:</u>		
[] - Span	movement - horizontally as w	ell as vertically		
1. C	Check displacement / deflectio	n along curb line, both bridge rails and outer edge of bridge deck.		
2. 0	Check for plumb of piers or be	nts.		
[] - Chec	k for embankment erosion			
[] - Chec	k for drift build-up on piers or	bents		
[] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection		
[] - Revie	w the latest bridge inspection	report versus current field conditions		
<u>lf Closure is</u>	recommended:			
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may		
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)		
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)		
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate		
	(4) TDOT Regional Bridge	Engineer		
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673		
TENNESSEE HIGHWAY PATROL	(731) 423-6635		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	tion:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade T			
SAFETY HAZARD KEEF	PAWAY		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)