HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: HAWKINS

BRIDGE ID NUMBER: 37025450001
BRIDGE OWNER: HAWKINS COUNTY
ROAD NAME: TUNNEL HILL RD

CROSSING: CHEROKEE LAKE-BEECH CR.
LATITUDE:: N 36.39793 DEGREES
LONGITUDE: W 82.92873 DEGREES

ROUTE: 02545
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.58

	GITUDE: W 82.92873 DEGREE	YEAR BUILT: 1965
LON	OHODE. W 62.92073 DEGREE	TEAR BOILT. 1303
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/ GIRDER	MULTI-BEAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMI	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Checl [] - Checl [] - Revie	check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a w the latest bridge inspection	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
f Closure is	recommended:	
Coun temp	ty or City Maintenance Perso	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	• •	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	``	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	•
	Bridge should remain closed u FDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 272-7359		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 272-7370		
COUNTY SHERIFF'S OFFICE	(423) 272-4848		
[] - Summarize and submit findings from the inspect The report shall include the date and time of the as appropriate, photographs of the bridge and street scouring has occurred, the report shall also be considered.	inspection, a brief summary of findings and, tream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>n:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tap			
SAFETY HAZARD KEEP A	WAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24