## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 38008470003

BRIDGE OWNER: Haywood County

ROAD NAME: THREE FORKS CHURCH RD.

CROSSING: DRY HOLLOW CREEK

LATITUDE:: N 35.543861 DEGREES

LOG MILE: 1.09

LONGITUDE: W -89.17925 DEGREES	LOG MILE: 1.09 YEAR BUILT: 1979
MAIN SPAN: Concrete Continuous Culvert	APPR. SPAN: None  TYPE OF SUBSTRUCTURE
ABUTMENTS: Concrete Box on Concrete Spreader Spr	ead Footing
Bridge is scour critical; Countermeasures h reduce the risk of bridge failure during a flo	ave been installed to mitigate an existing problem with scour and to bood event.  INSPECTION PROCEDURES
What Initiated the Call-out Inspection?	[ ] BridgeWatch Alert [ ] TDOT District or Local Maintenance Personnel [ ] THP or Local Law Enforcement Personnel [ ] Other:
2. Check for plumb of piers or ber     3. Check for embankment erosion     4. Check for drift build-up on piers or ber     5. Check pier exposure, if possible, and a second control of the check pier exposure.	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
County or City Maintenance Person temporary measures to warn motor be properly closed and barricaded.	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
(2) City or County Highway (3) Tennessee Highway Pa (4) TDOT Regional Bridge	upervisor ( if bridge is State maintained ) y Maintenance Official ( if bridge is not State maintained ) atrol and/or local law enforcement Officers as appropriate Engineer htil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



	icials in establishing a detour route. Any bridge on the or to signing the detour route.	selected detour route shall be checked
	e bridge can be re-opened only after a TDOT bridge ins its and they are determined to be structurally stable.	pection team checks the substructure
CO	NTACT PERSONNEL:	TELEPHONE NUMBER:
HW	INTY MAYOR'S OFFICE Y. CHIEF ADMINISTRATOR'S OFFICE INTY SHERIFF'S OFFICE	(731) 772-1432 (731) 772-9423 (731) 772-6158`
The as a	marize and submit findings from the inspection to Brid report shall include the date and time of the inspection ppropriate, photographs of the bridge and stream char uring has occurred, the report shall also be copied to B	n, a brief summary of findings and, nnel measurements. If significant
COMMENT	S:	
Suggeste	d List of Equipment to conduct the Inspection:	
Latest Bri	dge Inspection Report	
Scour PO	A Report with the above Checklist	
Bridge De	sign Plans, if available	
Tape mea	sure with weight	
Plumb bo	•	
Range Po		
A 1000 Fo	ot Roll of yellow Polyethylene Barricade Tape printed v	vith the following message:

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

**SAFETY HAZARD KEEP AWAY** 

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT** radio directory (State Personnel only)