HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 380A1500001

BRIDGE OWNER: HAYWOOD COUNTY

ROAD NAME: POWELL RD

CROSSING: BIG BLACK CREEK

LATITUDE:: N 35.46481 DEGREES LONGITUDE: W 89.08290 DEGREES

COUNTY: HAYWOOD
ROUTE: 0A150
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.57
YEAR BUILT: 2023

		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		NOT APPLICABLE
ABUTMENTS: BENTS: PIERS:	TIMBER CAP ON TIMBER MUDSILL NOT APPLICABLE NOT APPLICABLE	- TYPE OF SUBSTRUCTURE - FOUNDATION	
Bridge has I	unknown foundations. Risk of so	SCOUR EVALUATION =	bridge shall be monitored for distress
	ficant flood events. Monitor bridge		
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] THP or Local Law En	al Maintenance Personnel forcement Personnel
Things to c	heck on a bridge during floods	s:	
1. 0 2. 0 [] - Chec [] - Chec	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	n along curb line, both bridgents. bents nd compare to previous inspe	
If Closure is	recommended:		
Cour temp] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.		
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	` '		ement Officers as appropriate
	(4) TDOT Regional Bridge	_	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 772-1432		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 772-9423		
COUNTY SHERIFF'S OFFICE	(731) 772-6158		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	ction:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	Tomo mainted with the following areas as		
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFETY HAZARD KEE	P AWAT		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24