## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 39016980001

BRIDGE OWNER: **STATE OF TENNESSEE**ROAD NAME: **SARDIS SCOTTS HILL RD** 

CROSSING: FLAT CREEK

LATITUDE:: N 35.59528 DEGREES
LONGITUDE: W 88.21681 DEGREES

COUNTY: HENDERSON
ROUTE: SR201
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 13.21

LON	NGITUDE: W 88.21681 DEGREES	YEAR BUILT: 1980
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE CONTIL STRINGER/MULTI-BEAM OR GIRDE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
BENTS:	CONCRETE PILE BENT ON PILE FO	UNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
	our critical; bridge foundations de ling scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
	•	[ ] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[ ] Other:
1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or bei k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. ats.
If Closure is	recommended:	
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made FDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673		
TENNESSEE HIGHWAY PATROL	(731) 423-6635		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	tion:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade T			
SAFETY HAZARD KEEF	PAWAY		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)