HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 390A2130001 COUNTY: HENDERSON

BRIDGE OWNER: HENDERSON COUNTY

ROAD NAME: BOREN RD CROSSING: BIG CREEK

LATITUDE:: N 35.63833 DEGREES

ROUTE: 0A213 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.34

LON	IGITUDE: W 88.20544 DEGREES		YEAR BUILT: 1968
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
	our critical; bridge foundations de sures are installed but they are n		lculated scour conditions. No scour
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous insp	
f Closure is	recommended:		
Coun temp	ty or City Maintenance Persor	inel. Use Barricade Tape, tra ists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any bi prior to signing the detour route.	ridge on the selected detour route shall be checked	
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substruunits and they are determined to be structurally stable. 		
2	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
C	COUNTY MAYOR'S OFFICE	(731) 968-0122	
H	HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 968-9201	
C	COUNTY SHERIFF'S OFFICE	(731) 968-7777	
a s			
Sugges	sted List of Equipment to conduct the Inspec	tion:	
Latest	Bridge Inspection Report		
Scour I	POA Report with the above Checklist		
Bridge	Design Plans, if available		
•	neasure with weight		
Plumb			
Range			
A 1000	Foot Roll of yellow Polyethylene Barricade T		
	SAFETY HAZARD KEEF	PAWAY	

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape