## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 390A7600001 COUNTY: HENDERSON

BRIDGE OWNER: HENDERSON COUNTY

ROAD NAME: **FEATHERS LN** CROSSING: **BRANCH** 

ROUTE: 0A760
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.29

	TITUDE:: N 35.71006 DEGREE			
LON	IGITUDE: W 88.58742 DEGREE:	S YEAR BUILT: 1960		
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MI GIRDER	JLTI-BEAM OR APPR. SPAN: NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	JNDATION		
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
Bridge has u	inknown foundations. Risk of sc	our cannot be determined. The bridge shall be monitored for distress		
		e in lieu of installing scour countermeasures.		
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert		
		[ ] TDOT District or Local Maintenance Personnel		
		[ ] THP or Local Law Enforcement Personnel		
		[ ] Other:		
Things to cl	heck on a bridge during flood	<u>s:</u>		
[ ] - Span	movement - horizontally as w	vell as vertically		
1. 0	Check displacement / deflection	on along curb line, both bridge rails and outer edge of bridge deck.		
2. 0	Check for plumb of piers or be	nts.		
[ ] - Checl	k for embankment erosion			
[ ] - Checl	k for drift build-up on piers or	bents		
[ ] - Check pier exposure, if possible, and compare to previous inspection				
[ ] - Review the latest bridge inspection report versus current field conditions				
lf Closure is	recommended:			
		serves read until bridge is accurred and preparity along by District		
		ncross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as		
temp	orary measures to warn moto	rists to stay off of the bridge until such time as the bridge may		
-	operly closed and barricaded			
[ ] - Conta	• •	Supervisor ( if bridge is State maintained )		
		ay Maintenance Official (if bridge is not State maintained)		
		atrol and/or local law enforcement Officers as appropriate		
, ,	(4) TDOT Regional Bridge	•		
	Bridge should remain closed । TDOT bridge inspection team.	Intil the water recedes and a daylight visual inspection is made		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



0	<ul> <li>The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.</li> </ul>		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>C</u>	ONTACT PERSONNEL:	TELEPHONE NUMBER:	
С	OUNTY MAYOR'S OFFICE	(731) 968-0122	
Н	WY. CHIEF ADMINISTRATOR'S OFFICE	(731) 968-9201	
С	OUNTY SHERIFF'S OFFICE	(731) 968-7777	
Th as	ummarize and submit findings from the inspect ne report shall include the date and time of the sappropriate, photographs of the bridge and stouring has occurred, the report shall also be considered.	inspection, a brief summary of findings and, ream channel measurements. If significant	
COMMEN	NTS:		
<u>Sugges</u>	ted List of Equipment to conduct the Inspectio	<u>n:</u>	
Latest E	Bridge Inspection Report		
Scour P	OA Report with the above Checklist		
•	Design Plans, if available		
•	easure with weight		
Plumb b			
Range F			
A 1000 l	Foot Roll of yellow Polyethylene Barricade Tap		
	SAFETY HAZARD KEEP A	WAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**