HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 400A1400001
BRIDGE OWNER: HENRY COUNTY
ROAD NAME: ROWE SCHOOL RD
CROSSING: ROWE CREEK

LATITUDE:: N 36.39447 DEGREES
LONGITUDE: W 88.32528 DEGREES

COUNTY: HENRY
ROUTE: 0A140
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.50
YEAR BUILT: 1981

LON	NGITUDE: W 88.32528 DEGREES	YEAR BUILT: 198	31
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUNI	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for e in lieu of installing scour countermeasures.	distress
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	ell as vertically n along curb line, both bridge rails and outer edge of br nts.	idge deck.
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed bunel. Use Barricade Tape, traffic cones and/or traffic flare ists to stay off of the bridge until such time as the bridge	es as
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)	
	``	y Maintenance Official (if bridge is not State maintaine	•
	``	atrol and/or local law enforcement Officers as appropria	te
	(4) TDOT Regional Bridge	•	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 642-5212		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 642-3162		
COUNTY SHERIFF'S OFFICE	(731) 642-1672		
 Summarize and submit findings from the inspection. The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be 	ne inspection, a brief summary of findings and, stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade Ta	and printed with the following massage:		
SAFETY HAZARD KEEP			

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape