HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 400A3930001
BRIDGE OWNER: HENRY COUNTY
ROAD NAME: WIMBERLY RD
CROSSING: TURKEY PEN BRANCH

LATITUDE:: N 36.32241 DEGREES
ONGITUDE: W 88.23763 DEGREES

COUNTY: HENRY
ROUTE: 0A393
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.35
YEAR BUILT: 2004

LONGITUDE: W 88.23763 DEGREES			YEAR BUILT: 2004	
MAIN ODAN	CONODETE CHANNEL DEAM	TYPE OF SUPERSTRUCTURE	NOT APPLICABLE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE	
		 TYPE OF SUBSTRUCTURE 		
	CONCRETE FULL HEIGHT ABUTM	ENT ON UNKNOWN FOUNDATION		
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
	unknown foundations. Risk of so ficant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.	
		- INSPECTION PROCEDURES -		
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert		
		[] TDOT District or Loca	al Maintenance Personnel	
		[] THP or Local Law En	forcement Personnel	
		[] Other:		
Things to c	heck on a bridge during flood	' <u>s:</u>		
_	movement - horizontally as v			
		•	e rails and outer edge of bridge deck.	
	Check for plumb of piers or be			
[] - Chec	k for embankment erosion			
[] - Chec	k for drift build-up on piers o	bents		
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspe	ection	
[] - Revie	ew the latest bridge inspection	n report versus current field c	onditions	
lf Closure is	recommended:			
		across road until bridge is sec	cured and properly closed by District,	
			ffic cones and/or traffic flares as	
			until such time as the bridge may	
-	roperly closed and barricaded		maintained \	
[] - Conta	act: (1) District Maintenance		•	
	``	Patrol and/or local law enforce	idge is not State maintained)	
	(4) TDOT Regional Bridge		ment Officers as appropriate	
[].The	` '		davlight visual inspection is made	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 642-5212		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 642-3162		
COUNTY SHERIFF'S OFFICE	(731) 642-1672		
[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	ection:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	Tone printed with the fellowing process.		
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFETY HAZARD KEI	EP AWAT		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24