HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: HUMPHREYS

BRIDGE ID NUMBER: 43018060001

BRIDGE OWNER: HUMPHREYS COUNTY
ROAD NAME: E BIG RICHLAND CIR
CROSSING: DEER CREEK

LATITUDE:: N 36.16258 DEGREES
LONGITUDE: W 87.75327 DEGREES

ROUTE: 01806
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.08

LON	NGITUDE: W 87.75327 DEGREES		YEAR BUILT: 1970
MAIN SPAN:	PRESTRESSED CONCRETE - BOX E GIRDERS - SINGLE OR SPREAD	TYPE OF SUPERSTRUCTURE BEAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	BUTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	STEEL PILE FOUNDATION	
		SCOUR EVALUATION -	
	our critical; field review indicates o provide scour countermeasures		red at bridge foundations. Immediate action alling scour countermeasures.
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or ben isk for embankment erosion isk for drift build-up on piers or isk pier exposure, if possible, ar ew the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
[] - Stay Cour temp	nty or City Maintenance Person	nel. Use Barricade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Cont	act: (1) District Maintenance S (2) City or County Highwa (3) Tennessee Highway Pa (4) TDOT Regional Bridge	y Maintenance Official (if bo atrol and/or local law enforce Engineer	e maintained) ridge is not State maintained) ement Officers as appropriate daylight visual inspection is made
by a	TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State I officials in establishing a detour route. Any bridge prior to signing the detour route. 			
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>ı:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	e printed with the following message:		
SAFETY HAZARD KEEP AV			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19