HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 430A1500001

BRIDGE OWNER: HUMPHREYS COUNTY

ROAD NAME: TRACE CR RD CROSSING: TRACE CREEK

COUNTY: HUMPHREYS ROUTE: 0A150 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	NTITUDE:: N 36.10562 DEGREES NGITUDE: W 87.70952 DEGREES	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE CONTIL BEAM OR GIRDERS - SINGLE OR S	
		TYPE OF SUBSTRUCTURE -
	CONCRETE STUB ABUTMENT ON S	
BENTS:	STEEL PILE BENT ON PILE FOUND	ATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION -
	our critical; bridge foundations de stalled and is in good condition.	termined to be unstable for calculated scour conditions. Rip-rap protection
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or being the control of th	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>If Closure is</u>	recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
 - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Insp Latest Bridge Inspection Report Scour POA Report with the above Checklist	ection:		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:		
SAFETY HAZARD KE	EP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24